W24

OK

Michael O. Leavitt Governor

Robert L. Morgan Executive Director Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 (801) 538-5340 telephone (801) 359-3940 fax (801) 538-7223 TTY

www.nr.utah.gov

INSPECTION REPORT

Partial	_Complete XXX Exp	loration
Inspection Date:	09/24/2002 / Time: 1	0:30 to 3:00
	ate of Last Inspection:	

Mine Name: Bear Car	nyon Mine	County: Emery	Permit Number: <u>C/015/025</u>
Permittee and/or Oper	ator's Name: <u>(</u>	Co-Op Mining Company	
Business Address:	P.O. Box 124	45, Huntington, Utah 845	28
Company Official(s):	Mark Reynold	S	
State Official(s):	Joe Helfrich	_Federal Official(s):N	lone
Weather Conditions: _	Sunny, Clea	r, Windy about 75 degre	es
Type of Mining Activi	ty: Undergrou	nd XXX Surface Pr	ep PlantOther
Existing Acreage: Per	mitted_3336.	18 Disturbed 37.17	Regraded Seeded
Status: Active XXX			

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]		[X]	
2.	SIGNS AND MARKERS	$\overline{[X]}$	ĹĴ	[X]	
3.	TOPSOIL	$\overline{[X]}$	ĹÌ	[X]	. [_]
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[X]		[X]	[_]
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[X]		[X]	
c.	OTHER SEDIMENT CONTROL MEASURES	[X]		[X]	
d.	WATER MONITORING	[X]		[X]	
e.	EFFLUENT LIMITATIONS	[X]		[X]	
5.	EXPLOSIVES	[X]		[X]	
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES		[X]		
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS		[X]		
8.	NONCOAL WASTE	[X]		[X]	
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES		[X]		
10.	SLIDES AND OTHER DAMAGE		[X]		
11.	CONTEMPORANEOUS RECLAMATION	[X]		[X]	
12.	BACKFILLING AND GRADING		[X]	\Box	
13.	REVEGETATION	[X]		[X]	Ļ
14.	SUBSIDENCE CONTROL	[X]			Ц
15.	CESSATION OF OPERATIONS		[X]		
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[X]		[X]	1.1
b.	DRAINAGE CONTROLS	[X]		[X]	
17.	OTHER TRANSPORTATION FACILITIES	[X]			
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS		[X]		
19.	AYSTHECK (4 th Quarter- April, May, June)		[X]		
20.	AR THALLY PERMIT	[X]		[X]	
21.	BONDING LINSURANCE	[X]		[<u>X</u>]	

INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: C/015/025

DATE OF INSPECTION: 09/24/2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The permit for this operation is valid through 11/02/2005. The following amendments are pending;

AM02B-1	TANK SEAM
AM02F	BTCA AREA
AM02G-1	WATER MONITORING UPDATE
AM02D	VEGETATION REFERENCE

Clean copies of the Tank seam are due on 10/01/2002. A deficiency response to the BTCA area is due on 09/30/2002. The review of the water monitoring update is due on 09/30/2002. The review of the reference area is due on 10/15/2002.

2. SIGNS AND MARKERS

The main sign at the mine entrance is in place along with Stream Buffer Zone signs and Topsoil Storage Pile signs.

3. TOPSOIL

Topsoil storage piles along the Tank Seam Road and the main minesite road are in good condition with no indications of erosion.

4A. HYDROLOGIC BALANCE: DIVERSIONS

All culverts and ditches are cleaned out. Inlets and outlets were inspected.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

Sediment pond A has been cleaned out.

Pond B has water in it. It is being cleaned out as weather permits.

Pond C is dry with no sediment accumulation in it.

All three sediment ponds were inspected under the direction of a Registered Professional Engineer on April 10, 2002. The inspection forms were reviewed and need to be signed.

Sediment Pond D has not yet been constructed at the top of the Wild Horse Ridge road.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

Erosion control matting is in place along the entire length of the road at the construction of the Wild Horse Ridge addition.

4D. HYDROLOGIC BALANCE: WATER MONITORING

Water monitoring reports, both lab and as reported, were inspected. All sites had all the required parameters reported.

INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: C/015/025 DATE OF INSPECTION: 09/24/2002

4E. HYDROLOGIC BALANCE: EFFLUENT LIMITATIONS

All UPDES Discharge Monitoring Reports, DMRs, were inspected and found to be complete. There was no discharge at any of them during the second quarter of this year. The permit is valid through 04/30/2003.

5. EXPLOSIVES

The vent openings for both the powder and detonator magazines have been thoroughly cleaned out from rocks and debris from recent storms.

8. NONCOAL WASTE

The site was clear of noncoal waste.

11. CONTEMPORANEOUS RECLAMATION

The Tank Seam portals have been sealed per the MRP. The steel surface structures were pulled from the portals with rock falls taking place as they were pulled. Backfilling of the portals has been completed and approximately 30 yards of the road has been reclaimed.

13. REVEGETATION

Reclamation activities at the tank seam will be seeded this Fall.

16A. ROADS: CONSTRUCTION/MAINTENANCE/SURFACING

Roads were all bladed and in good condition. They need to be sprinkled with water for dust control as soon as the new water system is completed.

16B. ROADS: DRAINAGE CONTROLS

The ditches and culverts were all in good condition.

17. OTHER TRANSPORTATION FACILITIES

The new Tank Seam portal is immediately adjacent to Forest Service property. Therefore, the mine is having the property line between them and the Forest Service surveyed. They have the appropriate State of Utah agency and Forest Service coordinated to do this. The cost will be split between the mine and state agency. Surveying commenced September 30, 2002.

INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: C/015/025

DATE OF INSPECTION: 09/24/2002

20. AIR QUALITY PERMIT

A new air quality permit was issued on February 22, 2002 and is available at the mine. The number is DAQE-862-99 and includes the increased production of the Wild Horse Ridge expansion.

21. BONDING AND INSURANCE

The Bonding Agreement is in place as of June 28, 2001 in the amount of \$1,825,000. It's with Lyndon Property Insurance Co. It remains in effect until all parties perform at reclamation time.

There is a Certificate of Liability Insurance in place with an expiration date of 01/01/2003. The coverage is the same as before and meets regulatory requirements.

Inspector's Signature:

Joseph C. Helfrich #1

Date: September 30, 2002

Note:

This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc:

James Fulton, OSM

Wendell Owen, Co-Op Mining

Price Field office

 $O: \verb|\|015025.BCN\|DRAFT\|C_0924.doc|$